

UNCLASSIFIED

---

AD 273 722

*Reproduced  
by the*

ARMED SERVICES TECHNICAL INFORMATION AGENCY  
ARLINGTON HALL STATION  
ARLINGTON 12, VIRGINIA



---


UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

222

CTIA

273 722



TECHNICAL REPORT

DC-TR: 1-4-62

EVALUATION  
OF  
MASK, ANTIFLASH, ROCKET LAUNCHER, M19A1

BY  
ELBERT HUSELTON  
PAUL SCHINDLER

AG 11A  
APR 1 1962  
67-7-6  
A

COPY NO. 14 OF 33

MARCH 1962

AMMUNITION GROUP

PICATINNY ARSENAL - DOVER, NEW JERSEY

TECHNICAL REPORT

EVALUATION  
OF  
MASK, ANTIFLASH, ROCKET LAUNCHER, M19A1

BY

ELBERT HUSELTON

PAUL SCHINDLER

Report No. DC-TR: 1-4-62

SUBMITTED BY:

*F. Sedlacek*  
F. SEDLACEK  
Chief, Maintenance  
Engineering Section

REVIEWED BY:

*H. Rutkovsky*  
H. RUTKOVSKY  
Chief, Ammunition  
Engineering Branch

REVIEWED BY:

*D. Katz*  
D. KATZ  
Chief, Process  
Engineering Branch

APPROVED BY:

*J. J. Matt*  
J. J. MATT  
Chief, Ammunition  
Production & Maint  
Engineering Division

58

## TABLE OF CONTENTS

Section		Page
I	INTRODUCTION	1
II	SUMMARY	3
III	CONCLUSIONS	3
IV	RECOMMENDATIONS	5
V	STUDY	7
	REFERENCES	11
	APPENDICES	
	A. Tables	A1-2
	B. Figures	B1-14
	C. Letters	C1-3
	TABLE OF DISTRIBUTION	i

## SECTION I

### INTRODUCTION

Various malfunctions were reported in 1959 and early 1960 in which firing of the 3.5 Inch Rocket, M28A2 and M29A2, resulted in excessive blowback. In all these malfunctions (MIFs A-110-59, A-1-60, A-124-60, A-188-60), personnel received cuts, burns or abrasions from blowback of unburned propellant particles in the rocket exhaust -- in some instances even when they were wearing the Mask, Antiflash, Rocket Launcher, M19.

In 1960 these malfunctions, in addition to earlier reported incidents of the same nature, resulted in a series of test firings at Aberdeen Proving Ground in which rockets were investigated for blowback and for adequacy of protection furnished by the M19 Antiflash Mask. The findings showed blowback to be prevalent at all low temperature firings, with both penetration and lens breakage occurring in the M19 Antiflash Mask. Based on this, the weapon was restricted from use at temperatures below freezing (32°F.) pending redesign of the M19 Antiflash Mask.

In January 1961, a firing program was conducted by Picatinny Arsenal (Reference 1) to: 1) determine whether this excessive blowback was due to degradation of the rocket motors in storage 2) measure the variation of blowback with temperature 3) determine whether the Mask, Protective, Field, M9A1 (Gas Mask) furnished adequate protection as an interim measure pending development and prove-out of an improved rocket anti-flash face mask. Results of this study indicated that: 1) blowback on firing 3.5 inch rockets at temperatures less than 70°F. was inherent in

the design and did not reflect an aging problem 2) the 3.5 Inch Rocket was satisfactory for firing at all temperatures to -20°F., provided adequate face and eye protection was worn 3) Mask, Protective, Field, M9A1 was entirely satisfactory for repeatedly withstanding blowback from rounds conditioned for maximum blowback (-20°F.).

Based on these tests, the Ordnance Ammunition Command lifted the 32°F. temperature restriction on all M28 and M29 Series Rockets by world-wide teletype February 1961. Instructions were issued that: 1) eye protection in the form of goggles or similar equipment was mandatory for operating personnel when firing 3.5 inch rockets at temperatures of 70°F. and above 2) face and hand protection was necessary at all temperatures below 70°F. 3) Mask, Protective, Field, M9A1, was prescribed for face protection 4) other types of face protection were no longer authorized.

In June 1961, 20 M19A1 Antiflash Masks were shipped to Picatinny Arsenal for simulated service tests with cold-conditioned rounds of 3.5 Inch Rockets and for general comment relative to adequacy of the mask for the intended use (Appendix C). The purpose of the test program covered by this report, therefore, was to evaluate the adequacy of the M19A1 Antiflash Mask, developed by the Chemical Corps Engineering Command as a replacement for the M19 Antiflash Mask.

A summary of the test results was forwarded to the Chemical Corps on 6 Sept 1961.

## SECTION II

### SUMMARY

Two series of 3.5 Inch Rocket firings at -20°F. were run to observe the effect of rocket blowback on the M19A1 Antiflash Mask.

In the first series -- consisting of 20 firings. -- the mask was mounted six inches aft of the launcher bell-mouth. In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blowback. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

## SECTION III

### CONCLUSIONS

The Mask, Antiflash, Rocket Launcher, M19A1 provides adequate protection against 3.5 Inch Rocket blowback, but design of the mask is not optimum from a human engineering standpoint.



SECTION IV  
RECOMMENDATIONS

1. Consideration to be given design modifications including:
  - a. Permanently fastening the eyepiece to the mask portion.
  - b. Providing more effective shielding at the sides of the eyepiece.
2. Other human engineering factors, such as those affecting aim or comfort be evaluated.
3. After completion of human engineering, the Mask, Antiflash, Rocket Launcher, M19A1 be worn when firing M28 and M29 Rocket series at all temperatures below 70°F.
4. Eye protection in the form of goggles or similar equipment be worn when firing 3.5 Inch Rockets at temperatures of 70°F. and above.

ACTION TAKEN

The results of this evaluation, along with recommendations for human engineering, were forwarded to the Chemical Corps 6 September 1961 (Reference 2).

## SECTION V

### STUDY

Two series of 20 flight firings at  $-20^{\circ}\text{F}$ . were made to evaluate the effect of 3.5 Inch Rocket blowback on the Mask, Antiflash, Rocket Launcher, M19A1.

In the first series, a rectangular board, with a hole cut out of the center for the launcher, was positioned perpendicular to the launcher axis at a distance six inches aft of the launcher muzzle. The board surface was covered with a four-inch thick layer of foam rubber. One M19A1 Antiflash Mask and one M19 Antiflash Mask (used for comparison purposes) were mounted on the board (Figure 1). Blowback witness sheets, to provide semi-quantitative measurements of the extent of blowback, were mounted on the other side of the launcher. At five-round intervals, the positions of the masks were reversed to minimize the effect of mask position as a variable (Figures 2-4).

The standards used in grading blowback witness sheets (Figures 5a-5e) are:

<u>Blowback</u>	<u>Description</u>
0	No penetration
1	Very lightly peppered
2	Lightly peppered
3	Moderately peppered
4	Heavily peppered
5	Severely peppered

The results of these firings are summarized in Table 1. The average blowback ranking of 4.5 showed that the test lot of rockets produced a relatively large amount of unburned propellant and, therefore, provided a good test of mask effectiveness.

As seen from Figure 6 and 7, the face covering of the M19 Mask was severely punctured. Also, one of the lens sustained a crack about  $3/8$ " long. The M19A1 Mask, however, suffered only four pinhole penetrations; three in the leather eyepiece support, and one in the lower part of the mask (Figure 8). One of the eyepieces had several shallow chips, but there was no cracking of the lens.

In the second series, only the M19A1 Mask was tested. The mask was mounted in a position corresponding to the gunner's head (Figure 9) and was not moved until the firings were completed. After 18 firings, no penetration of the mask or eyepiece was observed (Table II). Only a very few particles were found imbedded in the mask (Figure 10).

Based on these results, it was concluded that the M19A1 Antiflash Mask provides adequate face and eye protection when firing 3.5 Inch Rockets at  $-20^{\circ}\text{F.}$ , the low temperature firing limit for the 3.5 Inch Rocket and the condition in which the degree of blowback is most severe.

Although the materials used in the M19A1 Mask successfully resisted propellant blowback, it was considered that the design of the mask was not optimum from a human engineering standpoint because (1) the operator could inadvertently neglect to fasten all the snaps holding the eyepiece to the face portion (2) the screen on the side of the eyepiece could allow penetration of propellant particles if the mask was not properly worn or the head was turned to one side as the rocket was fired.

It was recommended, that consideration be given to modifying the design before issuance to the field including:

- 1) Permanently fastening the eyepiece to the mask portion.
- 2) Providing more effective shielding at the sides of the eyepiece.

## REFERENCES

1. E. Huselton, D. Eleasier and S. Kaplowitz, Evaluation of Blowback in the 3.5 Inch Rocket; M28A2, Picatinny Arsenal Technical Report No. DB-TR: 4-61, dated June 1961.
2. Letter to Commanding Officer, U. S. Chemical Corps Engineering Command, Army Chemical Center, Maryland from Commanding Officer, Picatinny Arsenal on evaluation of Mask, Antiflash, Rocket Launcher, M19 (Improved Type), dated 30 June 61. (Complete text in Appendix C.)

## APPENDICES

APPENDIX A

TABLES

Table I                      Series I

Results of Series I Firings at -20°F to Evaluate M19A1 Antiflash Mask

<u>Rd No.</u>	<u>Velocity Ft/Sec</u>	<u>Blowback Ranking</u>	<u>Remarks</u>
1	318	5	Position of masks shown in Figure 1
2	312	5	
3	315	5	
4	319	4	
5	311	4	Masks after firing of Round 5 shown in Figure 2
6	317	5	
7	318	4	
8	316	4	
9	313	5	
10	311	5	Masks after firing of Round 10 shown in Figure 3
11	309	5	
12	312	5	
13	320	5	
14	311	5	
15	310	4	Masks after firing of Round 15 shown in Figure 4
16	317	4	
17	321	4	
18	318	3	
19	310	5	
<u>20</u>	<u>311</u>	<u>5</u>	
Avg.	313	4.5	



Table II

Results of Series II Firings at -20°F to Evaluate M19A1 Antiflash Mask

<u>Rd No.</u>	<u>Velocity Ft/Sec</u>	<u>Remarks</u>
1	317	Firing Set-up Shown in Figure 9.
2	319	Firing Set-up Shown in Figure 9.
3	314	Firing Set-up Shown in Figure 9.
4	315	Firing Set-up Shown in Figure 9.
5	314	Firing Set-up Shown in Figure 9.
6	316	Firing Set-up Shown in Figure 9.
7	322	Firing Set-up Shown in Figure 9.
8	318	Firing Set-up Shown in Figure 9.
9	313	Firing Set-up Shown in Figure 9.
10	317	Firing Set-up Shown in Figure 9.
11	315	Firing Set-up Shown in Figure 9.
12	316	Firing Set-up Shown in Figure 9.
13	310	Firing Set-up Shown in Figure 9.
14	321	Firing Set-up Shown in Figure 9.
15	320	Firing Set-up Shown in Figure 9.
16	312	Firing Set-up Shown in Figure 9.
17	307	Firing Set-up Shown in Figure 9.
<u>18</u>	<u>320</u>	Firing Set-up Shown in Figure 9.
Avg.	316	

## APPENDIX B

### FIGURES




Figure 1. Test Set Up for Series 1 Firing




Figure 2. Masks After Firing of Round 5, Series 1




Figure 3. Masks After Firing of Round 10, Series I




Figure 4. Masks After Firing of Round 15, Series I

# 120 - 0 + 700 700  
DEGREE OF PENETRATION 0

Figure 5A. Typical Witness Sheet for Degree of Penetration #1  
Very Lightly Peppered



Figure 5B. Typical Witness Sheet for Degree of Penetration #2,  
Lightly Peppered





Figure 5C. Typical Witness Sheet for Degree of Penetration #3,  
Moderately Peppered



Figure 5D. Typical Witness Sheet for Degree of Penetration #4,  
Heavily Peppered




Figure 5E. Typical Witness Sheet for Degree of Penetration #5,  
Severely Peppered



Figure 6. M19 Mask After Exposure to 20 Firings, Series I



Figure 7. M19 Mask Showing Cracked Left Lens After Exposure to  
20 Firings, Series I



Figure 8. M19A1 Mask After Exposure to 20 Firings, Series I



Figure 9. Test Set Up for Firing of Rounds 1-18, Series II




Figure 10. M19A1 Mask After Exposure to 18 Rounds in the Position of  
the Gunner's Head, Series II



APPENDIX C

LETTERS

HEADQUARTERS  
U.S. ARMY CHEMICAL CORPS ENGINEERING COMMAND  
ARMY CHEMICAL CENTER, MARYLAND

IN REPLY REFER TO:

CMLN-WSP

30 June 1961

SUBJECT: Mask, Antiflash, Rocket Launcher, M19 (Improved Type)

TO: Commanding Officer  
ATTN: ORDBB-DC5  
Picatinny Arsenal  
Dover, New Jersey

**COPY**

1. Development and widespread use of the 2.6 in. Rocket (bazooka) during World War II resulted in a requirement for a mask to protect the eyes and face of the operators during firing operations. The item developed to meet this need was the Mask, Face, Launcher, Rocket, classified as a standard type by OMTIC Item No. 13-44, 28 July 1944. This mask consisted of M-1943 Goggles to which thin rubberized fabric skirtings were sewed. Subsequent to World War II, this mask was made obsolete by the Quartermaster Corps.

2. With the advent of the 3.5 in. Rocket Launcher, U.S. Continental Army Command (USCONARC) confirmed that a requirement existed for a mask to protect the gunner's face and eyes. It had been noted that during firing operations particles of propellant and occasionally an arming wire back flashed, impacted on and sometimes pierced the skin of the gunner. It was further noted that cold weather increased the quantity of this firing debris with which the gunner had to contend.

3. The Mask, Face, Launcher, Rocket, was not considered by USCONARC to be the optimum item to meet requirements of the 3.5 in. Rocket Launcher gunner but was considered usable and an item of issue until a more suitable replacement could be produced. The mask was recaptured from obsolescence and became a gained item of the Chemical Corps. It was type classified as a Standard B Item, Mask, Antiflash, Rocket Launcher, M19, by CCTC Item No. 3634 approved 29 September 1959. It became an item of issue pending availability of an improved type.

CMLLEN-WSP

30 June 1961

SUBJECT: Mask, Antiflash, Rocket Launcher, M19 (Improved Type)

4. Test run in July 1960 at Aberdeen Proving Ground showed that the M19 Mask was frail and not adequate for the intended use. The Chemical Corps then recommended that the Mask, Protective, Field, M9A1, be used in place of the M19 as an interim measure pending availability of an improved M19.

5. In accordance with discussions with your Messrs. Schaffer and Kester, 16 June 1961, 20 improved M19 Masks were shipped to Picatinny Arsenal 20 June 1961 for simulated service test with cold conditioned round of 3.5 in. rockets and general comment relative to adequacy of the mask for the intended use. Further work toward type classification of the item will be dependent upon results of these tests.

6. Results of tests and comments are requested.

FOR THE COMMANDER:

MAX KERSCHENSTEINER  
Chief, Product Engineering Division  
Dir/Weapons Systems Engineering

Cpy furnished:  
Lt Col R. J. Phillips,  
USCONARC Ln Off

REFERENCE 2

ORDBB-DC5 (30 Jun 61)                      1st Ind                      Mr RSchindler/pjb/5135  
SUBJECT: Mask, Antiflash, Rocket Launcher, M19 (Improved Type)

Ordnance Corps, Picatinny Arsenal, Dover New Jersey

TO: Commanding Officer, U.S. Army Chemical Corps Engineering Command  
ATTN: OMLN-WSP, Army Chemical Center, Maryland

1. Evaluation of the adequacy of the subject mask to provide protection against unburned propellant and other debris in firing the 3.5 inch rocket at low temperatures has been completed by this Arsenal. Two series of rocket firings were made at -20°F. In the first series, which consisted of 20 firings, the mask was mounted six inches aft of the launcher bell-mouth; in the position of the gunner's head. The firings showed that the M19A1 Mask did provide adequate protection against blowback, while the M19 Mask, tested in the first series of firings for comparison data, was badly damaged.

2. Although the materials used in the M19A1 Mask successfully resisted propellant blowback, it is considered that the design of the mask is not optimum from a human engineering standpoint; i.e., (1) the operator could inadvertently neglect to fasten all the snaps holding the eyepiece to the face portion, (2) the screen on the side of the eyepiece could allow penetration of propellant particles if the mask is not properly worn or the head is turned to one side as the rocket is fired. It is recommended, therefore, that consideration be given to modifying the design before issuance to the field, including the following:

- a. Permanently fastening the eyepiece to the mask portion.
- b. Providing more effective shielding at the sides of the eyepiece.

3. Other human engineering factors, such as those affecting aim or comfort, have not been evaluated. It is assumed that these factors will be considered before issuance of the mask.

4. A complete report of the above tests and recommendations will be published and forwarded to your Command by 1 January 1962.

FOR THE COMMANDER:

CC:  
OSWAC, ORDSW-A  
CONARC Liason Officer (Lt Col Boisvert)

COPY

**ABSTRACT DATA**

**ABSTRACT**

AD \_\_\_\_\_ Accession No. \_\_\_\_\_

Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1.

Elbert Huselton and Paul Schindler.

Technical Report DC-TR: 1-4-62, March 1962.  
11 pp, photographs, tables.  
Unclassified Report.

Two series of 3.5 Inch Rocket firings at -20°F  
were run to observe the effect of rocket blowback on  
the M19A1 Antiflash Mask.

In the first series -- consisting of 20 firings -- the  
mask was mounted six inches aft of the launcher  
bell-mouth. In the second series -- consisting  
of 18 firings -- the mask was mounted in a position  
corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask  
did provide adequate protection against 3.5 Inch  
Rocket blowback. The M19 Antiflash Mask, tested  
in the first series for comparison purposes, was  
badly damaged.

Study of the new (M19A1) mask indicated need for  
human engineering.

**UNCLASSIFIED**

1. Protective clothing.

- I. Huselton, Elbert
- II. Schindler, Paul
- III. Title: Mask, antiflash
- IV. M19A1 Antiflash masks.
- V. 3.5 Inch Rocket

**UNITERMS**

Mask  
Antiflash  
Rockets, 3.5 Inch  
Launcher  
M19A1  
Huselton, E.  
Schindler, P.

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Anti-flash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

I. Protective clothing

I. Huselton, Elbert

II. Schindler Paul

III. Title: Mask, Antiflash

IV. M19A1 Antiflash

masks

V. 3.5 Inch Rocket

**UNITERMS**

Mask

Antiflash

Rockets, 3.5 Inch

Launcher

M19A1

**UNCLASSIFIED**

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Anti-flash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

I. Protective clothing

I. Huselton, Elbert

II. Schindler Paul

III. Title: Mask, Antiflash

IV. M19A1 Antiflash

masks

V. 3.5 Inch Rocket

**UNITERMS**

Mask

Antiflash

Rockets, 3.5 Inch

Launcher

M19A1

**UNCLASSIFIED**

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Anti-flash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

I. Protective clothing

I. Huselton, Elbert

II. Schindler Paul

III. Title: Mask, Antiflash

IV. M19A1 Antiflash

masks

V. 3.5 Inch Rocket

**UNITERMS**

Mask

Antiflash

Rockets, 3.5 Inch

Launcher

M19A1

**UNCLASSIFIED**

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Anti-flash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

I. Protective clothing

I. Huselton, Elbert

II. Schindler Paul

III. Title: Mask, Antiflash

IV. M19A1 Antiflash

masks

V. 3.5 Inch Rocket

**UNITERMS**

Mask

Antiflash

Rockets, 3.5 Inch

Launcher

M19A1

**UNCLASSIFIED**

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blowback. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blowback. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blowback. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blowback. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

UNCLASSIFIED



AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

- I. Protective clothing
  - I. Huselton, Elbert
  - II. Schindler Paul
  - III. Title: Mask, Antiflash
  - IV. M19A1 Antiflash masks
  - V. 3.5 Inch Rocket
- UNITERMS

Mask  
Antiflash  
Rockets, 3.5 Inch  
Launcher  
M19A1

**UNCLASSIFIED**

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

- I. Protective clothing
  - I. Huselton, Elbert
  - II. Schindler Paul
  - III. Title: Mask, Antiflash
  - IV. M19A1 Antiflash masks
  - V. 3.5 Inch Rocket
- UNITERMS

Mask  
Antiflash  
Rockets, 3.5 Inch  
Launcher  
M19A1

**UNCLASSIFIED**

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

- I. Protective clothing
  - I. Huselton, Elbert
  - II. Schindler Paul
  - III. Title: Mask, Antiflash
  - IV. M19A1 Antiflash masks
  - V. 3.5 Inch Rocket
- UNITERMS

Mask  
Antiflash  
Rockets, 3.5 Inch  
Launcher  
M19A1

**UNCLASSIFIED**

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.  
(over)

**UNCLASSIFIED**

- I. Protective clothing
  - I. Huselton, Elbert
  - II. Schindler Paul
  - III. Title: Mask, Antiflash
  - IV. M19A1 Antiflash masks
  - V. 3.5 Inch Rocket
- UNITERMS

Mask  
Antiflash  
Rockets, 3.5 Inch  
Launcher  
M19A1

**UNCLASSIFIED**

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.

(over)

UNCLASSIFIED

1. Protective clothing

I. Huselton, Elbert  
II. Schindler Paul  
III. Title: Mask, Antiflash  
IV. M19A1 Antiflash  
masks

V. 3.5 Inch Rocket

UNITERMS

Mask  
Antiflash

Rockets, 3.5 Inch

Launcher  
M19A1

UNCLASSIFIED

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.

(over)

UNCLASSIFIED

1. Protective clothing

I. Huselton, Elbert  
II. Schindler Paul  
III. Title: Mask, Antiflash  
IV. M19A1 Antiflash  
masks

V. 3.5 Inch Rocket

UNITERMS

Mask  
Antiflash

Rockets, 3.5 Inch

Launcher  
M19A1

UNCLASSIFIED

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.

(over)

UNCLASSIFIED

1. Protective clothing

I. Huselton, Elbert  
II. Schindler Paul  
III. Title: Mask, Antiflash  
IV. M19A1 Antiflash  
masks

V. 3.5 Inch Rocket

UNITERMS

Mask  
Antiflash

Rockets, 3.5 Inch

Launcher  
M19A1

UNCLASSIFIED

AD \_\_\_\_\_ Accession No. \_\_\_\_\_  
Picatinny Arsenal, Ammunition Group  
Dover, New Jersey

**EVALUATION OF MASK, ANTIFLASH, ROCKET  
LAUNCHER, M19A1**

*Elbert Huselton, Paul Schindler*

Technical Report DC-TR: 1-4-62, March 1962, 11 pp.  
photographs, tables.  
Unclassified Report

Two series of 3.5 Inch Rocket firings at -20°F were run  
to observe the effect of rocket blowback on the M19A1  
Antiflash Mask.

In the first series --- consisting of 20 firings --- the mask  
was mounted six inches aft of the launcher bell-mouth.

(over)

UNCLASSIFIED

1. Protective clothing

I. Huselton, Elbert  
II. Schindler Paul  
III. Title: Mask, Antiflash  
IV. M19A1 Antiflash  
masks

V. 3.5 Inch Rocket

UNITERMS

Mask  
Antiflash

Rockets, 3.5 Inch

Launcher  
M19A1

UNCLASSIFIED

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

UNCLASSIFIED

UNITERMS

Huselson, E.  
Schindler, P.

In the second series -- consisting of 18 firings -- the mask was mounted in a position corresponding to the gunner's head.

The firings showed that the M19A1 Antiflash Mask did provide adequate protection against 3.5 Inch Rocket blow-back. The M19 Antiflash Mask, tested in the first series for comparison purposes, was badly damaged.

Study of the new (M19A1) mask indicated need for human engineering.

UNCLASSIFIED

UNCLASSIFIED

## TABLE OF DISTRIBUTION

# TABLE OF DISTRIBUTION

	Copy Number
1. Chief of Ordnance Department of the Army Washington 25, D. C. ATTN: ORDIM ORDTU ORDFA	1 2 3
2. Commanding General Ordnance Special Weapons-Ammunition Command Dover, New Jersey ATTN: ORDSW-A Lt. Col Boisvert, CONARC Liaison Officer Major Gunning, Marine Corps Liaison Officer	4 5 6
3. Commanding Officer Picatinny Arsenal Dover, New Jersey ATTN: ORDBB-VA6 ORDBB-DB ORDBB-DC ORDBB-NR ORDBB-DX1 ORDBB-DC5	7-11 12 13 14 15-16 17-25
4. Commanding General Ordnance Ammunition Command Joliet, Illinois ATTN: ORDLY-Q	26-27
5. Commanding General Army Ordnance Missile Command Huntsville, Alabama ATTN: Technical Library	28-29
6. Commanding General Research and Engineering Ground Army Chemical Center Edgewood, Maryland	30

# TABLE OF DISTRIBUTION (CONT'D)

	Copy Number
7. Commanding General Aberdeen Proving Ground Ballistic Research Laboratories Aberdeen, Maryland ATTN: ORDBG-BRL-W Technical Library	31 32
8. Chief, Bureau of Naval Weapons (FQQA) Navy Department Washington 25, D. C.	33
9. Commanding Officer Diamond Ordnance Fuze Laboratories Washington 25, D. C. ATTN: Technical Reference Section	34-35
10. Chief Chemical Officer Department of the Army Washington 25, D. C.	36
11. Commander Naval Ammunition Depot Crane, Indiana ATTN: CODE 4100	37
12. Commanding General Army Chemical Center Edgewood, Maryland ATTN: Technical Library	38-39
13. Commander Armed Services Technical Information Agency Arlington Hall Station Arlington 12, Virginia ATTN: TIPDR	40-50
14. Solid Propellant Information Agency Johns Hopkins University Applied Physics Laboratory Silver Spring, Maryland	51-52

**TABLE OF DISTRIBUTION (CONT'D)**

	<b>Copy Number</b>
<b>15. Commanding Officer Naval Ammunition Depot Seal Beach, California</b>	<b>53</b>